

OFFICE OF THE EXECUTIVE ENGINEER,
PUBLIC WORKS DIVISION, BHANDARA.

Web Site
WWW.mahapwd.gov.in

E-mail: bhandara_ee@mahapwd.gov.in

Phone No. 07183 252412
Fax No. 252412

Outword No PWDB/ 4175 /Tech/D.M /Build.safety Certificate/2024

Date: 24/04/2024

To, ✓
Principal,
Manosuman Public School, (CBSE)
Korambhi Road, Pauni.
Taluka-Pauni Distt. Bhandara. (M.S.)

Sub:- Requirement of school Building Safety Certificate

Ref:- our Letter No. MSPS/2024/120, Date:- 30/03/2024

:: SCHOOL BUILDING SAFETY CERTIFICATE ::

Certified that the existing building **Manosuman Public School, (CBSE)** Name of the Building or premises) at- **Korambhi Road, Pauni. Taluka-Pauni Distt. Bhandara. (M.S.)** (Address) comprised of **Ground Floor** basement(s) and **First Floor** (upper floor) owned/occupied by **Manosuman Public School, (CBSE) Taluka-Pauni Distt. Bhandara.** owner by **Manosuman Shikshan Santha** (name of the Institution) have complied with the Building safety requirement in accordance with national Building code Rules, and verified by **Deputy Engineer, P. W. Sub-Division, Pauni** (Name of Department/ Govt.) on **Date 22/04/2024** (date of inspection) in the presence of **Amit Malvi, manager MSPS** (name and addresses of the manager/Secretary or his representative) and that the building/premises is fit for occupancy up to classes **1st to XII** with effect from **Date 01/04/2024 to 31/03/2025** for a period of **1 year** in accordance with rule and subject to compliance of the specific condition as appended.

1. Detail Area Statement of School Building:

- a) Ground Floor super Built-up Area – 1765.90 Sqm.
b) First Floor super Built-up Area – 557.62 Sqm.

2. Nature of Defects if any:

- a) Foundation & Basement -- R.C.C. Foundation
b) Superstructure -- R.C.C. Framed Structure
c) Door & Windows -- Grill Door & Windows
d) Roof -- R.C.C. Slab
e) Flooring -- I.P.S. Flooring
f) Miscellaneous (Crackes, etc.) -- No

3. Any Major defects noticed which will render the building unsafe in any manner – No Any Major Defects are Noticed.

4. If is also certified that building are in good condition to run the school.

Place: Bhandara

(P.P. Thamke)

Executive Engineer
Public Works Division
Bhandara.